



To whom it may concern,

A couple of years ago we purchased an Atlas Copco L2C30 Underground development jumbo. This rig was running higher water flow & pressures that we do on any of our other rigs.

We started having a lot of dramas with our flushing head seal only lasting two shifts also a lot of pitting around our shanks this was just the start of our problems. After a few months of use we started failing a lot of water fittings, up to two a shift.

On close inspection of the fitting it was hollowed out. The quality of the water we were using was basically recycled water out the stope. Not ideal but better than some sites.

After hitting the last resort we ended up fitting a 21/2" Ecosoft Water Conditioner unit to the water inlet, we honestly did not think it was going to work. After about 3-4 weeks, after coming back from break, was when I noticed the difference, we had stopped doing water fittings & flushing head seals were lasting up to 7 days. After this we recommended them to another site which fitted one to their rig due to the harsh water conditions.

About 2 months ago we removed it, 1-2 weeks later we started corroding out fittings & have since re-fitted it. For our application it worked well I would not have believed it would work until we tested it. I have since recommended it to other people & companies.

Trevor Williamson | Maintenance Training Specialist

Barmenco Limited

390 Stirling Crescent, Hazelmere WA 6065

Locked Bag 2500, Midland WA 6936

T +61 8 9416 1000 F +61 8 9416 1092

M 0427 700 895

E trevorw@barmenco.com.au

www.barmenco.com.au



Rocket Boomer L2 C Similar to the drill rig used by Barmenco at Sunrise Dam
Images courtesy Atlas Copco Photo Archive